




VERIFY ALL DIMENSIONS.
DO NOT SCALE DRAWINGS.
REPORT ANY DISCREPANCIES, DISCOVERED
ERRORS, OR OMISSIONS TO THE LANDSCAPE
ARCHITECT BEFORE PROCEEDING.
IT IS ADVISED THAT CONTRACTORS CONTACT
THE LANDSCAPE ARCHITECT PRIOR TO
CONSTRUCTION TO ENSURE THE USE OF THE
LATEST REVISED DRAWINGS.
DRAWINGS AND SPECIFICATIONS ARE THE
PROPERTY OF THE LANDSCAPE ARCHITECT.




TREE PROTECTION
 HOARDING
 EXISTING TREES TO
 BE PRESERVED
 MINIMUM TREE PROTECTION
 ZONE (TPZ)
 VEGETATION
 NUMBER KEY
 VEGETATION
 NUMBER KEY
 EXISTING TREES TO
 BE REMOVED
 MINIMUM TREE PROTECTION
 ZONE (TPZ)

Matthew C. Gehres
MATTHEW C. GEHRES
International Society of Arboriculture
Certified Arborist #ON-1114A
Date: SEPTEMBER 25, 2018



X	X	X	X
No.	DATE.	REVISION.	BY.

It is the responsibility of the Contractor and/or Owner to ensure that the drawings with the latest revisions are used for construction.

STRYBOS BARRON KING
LANDSCAPE ARCHITECTURE

PROJECT

PROPOSED 2 STOREY
OFFICE BUILDING
1110 LORNE PARK RD
CITY OF MISSISSAUGA
JACAN CONSTRUCTION LTD.
SP 11/027 W2

DRAWING TITLE.

SCALE.
1 : 125

DATE. SEPTEMBER 2018

DRAWN BY.
SS


CHECKED BY.
CHECKED BY

	PROJECT No.
--	-------------

18-5255

DRAWING No.

V100



KEY	SPECIES	CALIPER IN (cm)	CROWN IN (m)	HEALTH G/I/P	STRUCTURE	COMMENTS	PRESERVATION	MIN. TP2	KEY
1	CRIMSON KING NORWAY MAPLE	64	12	GOOD	GOOD FORM	SEVERE SCAR ALONG STEM, LOWER LIMBS PRUNED	PRESERVE	3.6	1
2	SIBERIAN ELM	35-73	3	FAIR	MULTI-STEMMED	THREE STEMS, DIEBACK ON LOWER BRANCHES, WEAK CROTCH, SLIGHT DIEBACK IN CROWN	REMOVE	2.4	2
3	SIBERIAN ELM	21-27	8	POOR	MULTI-STEMMED	THREE STEMS, SEVERE DIEBACK THROUGHOUT, BASAL DECAY, INCLUDED BARK, WEAK CROTCH	REMOVE	1.8	3
4	REDBARK OAK	26-33	6	POOR	MULTI-STEMMED	FOUR STEMS, SEVERE DIEBACK THROUGHOUT, WEAK CROTCH	REMOVE	1.8	4
5	SIBERIAN ELM	43	7	FAIR	MULTI-STEMMED	ONE SIDED FORM, DOUBLE STEM, CROWDING BY ADJACENT TREE, DIEBACK ON LOWER BRANCHES	REMOVE	1.8	5
6	SIBERIAN ELM	43	7	FAIR	MULTI-STEMMED	NARROW FORM, DIEBACK ON LOWER BRANCHES, CROWDING BY ADJACENT TREE	REMOVE	1.8	6
7	SIBERIAN ELM	16-23	5	POOR	MULTI-STEMMED	THREE STEMS, NARROW FORM, SEVERE DIEBACK ON LOWER BRANCHES, CROWDING BY ADJACENT TREE, HIGH CROWN, INCLUDED BARK, WEAK CROTCH	REMOVE	3	7
8	SIBERIAN ELM	17 to 32	7	FAIR	MULTI-STEMMED	CLUSTER OF FOUR STEMS, INCLUDED BARK, WEAK CROTCH, DIEBACK ON LOWER BRANCHES	REMOVE	0	8
9	SIBERIAN ELM	17-20	6	POOR	MULTI-STEMMED	THREE STEMS, NARROW FORM, CROWDING BY ADJACENT TREE, DIEBACK ON LOWER BRANCHES, DIEBACK IN CROWN, INCLUDED BARK, WEAK CROTCH	REMOVE	1.8	9
10	SIBERIAN ELM	70	10	FAIR	MULTI-STEMMED	DIEBACK THROUGHOUT, DOUBLE STEM, WEAK CROTCH, BASAL DECAY, OPEN FORM	REMOVE	3	10
11	SIBERIAN ELM	16-29	7	FAIR	MULTI-STEMMED	THREE STEMS, LEANING, ONE SIDED FORM, CROWDING BY ADJACENT TREE, DIEBACK ON LOWER BRANCHES, WEAK CROTCH	REMOVE	1.8	11
12	SIBERIAN ELM	42	5	FAIR	MULTI-STEMMED	ONE SIDED FORM, CROWDING BY ADJACENT TREE, DIEBACK ON LOWER BRANCHES, INCLUDED BARK	REMOVE	3	12
13	SIBERIAN ELM	44	6	FAIR	MULTI-STEMMED	MULTI-LEADERS, ONE SIDED FORM, CROWDING BY ADJACENT TREE, DIEBACK ON LOWER BRANCHES	REMOVE	3	13
14	RED OAK	169	25	GOOD	GOOD FORM	MATURE, BROAD FORM, CAVITY IN NORTH SIDE OF STEM	PRESERVE	8.7	14
15	SIBERIAN ELM	13-18	8.0	GOOD	MULTI-STEMMED	DIEBACK ON LOWER BRANCHES, STEM SPLITS AT GRADE	PRESERVE	1.8	15
16	CEDAR HEDGE	5-10	1.5	GOOD	GOOD FORM	DENSE, WELL MAINTAINED HEDGE FLANKING THE ADJACENT PROPERTY LINE	PRESERVE	1.8	16
17	WHITE SPRUCE	30.0	8.0	GOOD	GOOD FORM	BRANCHING TO GRADE	REMOVE	2.4	17
18	RED OAK	25.0	10.0	GOOD	GOOD FORM	LOW BRANCHING	PRESERVE	1.8	18
19	WHITE PINE	20.0	6.0	GOOD	IRREGULAR FORM	SUBORDINATES FORM DUE TO CROWDING BY ADJACENT OAK	PRESERVE	1.8	19

(V100)

