

**Chart Details:**  
 Tree #: Inventoried trees were assigned an identification number.  
 Species: Includes the botanical name and common name of each tree.  
 DBH: Diameter in cm measured at 1.4 meters from the ground (diameter at breast height). DBH in ( ) is the square root of the sum of the squares for multi-stem trees.  
 Drip line: Radius of the drip line in meters.  
 Condition Rating: Overall condition rating from good to fair to poor based on overall health and structure.  
 Ownership: Trees are identified as Private; Private adjacent; Heritage; or City-owned. Trees are identified as boundary if they appear to be located on or over the property line of the subject site.  
 Action: Protect, injure or remove recommendations based on the site plans, and other actions to be taken.

Tree #	Species	DBH (cm)	Drip Line (m)	Condition Rating	Ownership	Action
701	sugar maple (Acer saccharum)	35.5	5	Poor	private	Remove due to poor condition and for site access.
702	honey locust (Gleditsia triacanthos)	35	7.5	Good	private	Remove - within footprint of play amenity area.
703	Colorado spruce (Picea pungens)	38	3.5	Fair	private	Remove - within footprint of play amenity area.
704	honey locust (Gleditsia triacanthos)	40	4.5	Fair	private	Remove for underground garage excavation and shoring access and play amenity area.
705	honey locust (Gleditsia triacanthos)	53.5	8	Good	private	Remove for underground garage excavation and shoring access and play amenity area.
706	Austrian pine (Pinus nigra)	31.5	4	Fair	private	Remove due to underground parking excavation.
707	Austrian pine (Pinus nigra)	36	4	Fair	private	Remove due to underground parking excavation.
708	Austrian pine (Pinus nigra)	29.5	4	Fair	private	Remove due to underground parking excavation.
709	Austrian pine (Pinus nigra)	34	4	Good	private	Remove due to underground parking excavation.
710	Austrian pine (Pinus nigra)	38.5	3.5	Fair	private	Remove due to underground parking excavation.
711	honey locust (Gleditsia triacanthos)	39	7	Good	private	Remove - within footprint of underground parking.
712	honey locust (Gleditsia triacanthos)	42	6.5	Good	private	Remove - within footprint of underground parking.
713	Amur maple (Acer ginnala)	21, 13 (24)	6	Fair	private	Remove - within footprint of underground parking.
714	Amur maple (Acer ginnala)	28.5, 25.5 (38)	4.5	Fair	private	Remove - within footprint of underground parking.
715	Amur maple (Acer ginnala)	18	2.5	Poor	private	Remove - within footprint of underground parking.
716	Amur maple (Acer ginnala)	20, 17.5	4	Fair	private	Remove - within footprint of underground parking.
717	Amur maple (Acer ginnala)	14.8	3.5	Poor	private	Remove - within footprint of underground parking.
718	Amur maple (Acer ginnala)	21	3	Fair	private	Remove - within footprint of underground parking.
719	Amur maple (Acer ginnala)	16	3	Fair	private	Remove - within footprint of underground parking.
720	Amur maple (Acer ginnala)	17, 10.5 (20)	3	Fair	private	Remove - within footprint of underground parking.
721	Amur maple (Acer ginnala)	25 at 1.3m	4.5	Fair	private	Remove - within footprint of underground parking.
722	Amur maple (Acer ginnala)	13.5	1.5	Poor	private	Remove - within footprint of underground parking. <b>Permit not required.</b>
723	Amur maple (Acer ginnala)	20, 15, 17 (30)	3	Fair	private	Remove - within footprint of underground parking.
724	Amur maple (Acer ginnala)	18	2	Fair	private	Remove - within footprint of underground parking.
725	Amur maple (Acer ginnala)	28.5	3.5	Fair	private	Remove - within footprint of underground parking.
726	Amur maple (Acer ginnala)	15	1.5	Fair	private	Remove - within footprint of underground parking.
727	honey locust (Gleditsia triacanthos)	43	10	Good	private	Remove - within footprint of underground parking.
728	Russian olive (Elaeagnus angustifolia)	33	6	Fair	private	Remove - within footprint of underground parking.
729	honey locust (Gleditsia triacanthos)	36	7	Good	private	Remove - within footprint of underground parking.
730	Russian olive (Elaeagnus angustifolia)	39.5	6.5	Poor	private	Remove - within footprint of underground parking.
731	Russian olive (Elaeagnus angustifolia)	30, 27 (40)	8	Fair	private	Remove - within footprint of underground parking.
732	littleleaf linden (Tilia cordata)	46	6	Good	private	Remove - within footprint of underground parking.
733	littleleaf linden (Tilia cordata)	45.5	6	Good	private	Remove - within footprint of proposed building.
734	littleleaf linden (Tilia cordata)	32	4	Good	private	Remove - within footprint of proposed building.
735	Austrian pine (Pinus nigra)	30	4.5	Fair	private	Remove due to underground parking excavation.
736	Austrian pine (Pinus nigra)	40.5	5.5	Good	private	Remove - within footprint of proposed building.
737	Japanese tree lilac (Syringe reticulata)	12.5, 12, 10 (20)	5	Good	private	Remove - within footprint of underground parking.
738	Japanese tree lilac (Syringe reticulata)	17, 14, 9 (24)	3	Good	private	Remove - within footprint of underground parking.
739	Japanese tree lilac (Syringe reticulata)	17.5, 11, 10 (23)	4	Fair	private	Remove - within footprint of underground parking.
740	Japanese tree lilac (Syringe reticulata)	12, 11, 10 (19)	4	Fair	private	Remove - within footprint of underground parking.
741	Japanese tree lilac (Syringe reticulata)	16.5, 10, 9.5 (21)	3	Fair	private	Remove - within footprint of underground parking.
742	Japanese tree lilac (Syringe reticulata)	16, 12 (20)	3.5	Fair	private	Remove - within footprint of underground parking.
743	crabapple (Malus sp.)	30.5	5.5	Fair	private	Remove - within footprint of underground parking.
744	crabapple (Malus sp.)	29.5	5.5	Good	private	Remove - within footprint of underground parking.
745	Austrian pine (Pinus nigra)	44	5	Good	private	Remove - within footprint of underground parking.
746	Austrian pine (Pinus nigra)	35	4	Good	private	Remove - within footprint of underground parking.
747	Austrian pine (Pinus nigra)	31	4	Fair	private	Remove - within footprint of proposed seating area and wind/sound barrier.
748	Austrian pine (Pinus nigra)	30	4	Good	private	Remove - within footprint of proposed garden.
749	Austrian pine (Pinus nigra)	33	4.5	Good	private	Remove - within footprint of proposed garden/walkway.
750	European mountain ash (Sorbus aucuparia)	38 at 90 cm	3	Fair	private	Protect. Walkway excavation. Work must be carried out by hand and overseen by a qualified arborist.
751	European mountain ash (Sorbus aucuparia)	25, 26.5, 16 (45)	3.5	Good	private	Protect. Walkway excavation. Work must be carried out by hand and overseen by a qualified arborist.
752	European mountain ash (Sorbus aucuparia)	30, 20, 20 (36)	3.5	Fair	private	Protect. Walkway excavation. Work must be carried out by hand and overseen by a qualified arborist.
753	honey locust (Gleditsia triacanthos)	15	3.5	Good	private	Remove - in conflict with walkway and wind screen.
754	honey locust (Gleditsia triacanthos)	39	7	Good	private	Protect. Transformer pad and grading inside drip line. Minor clearance pruning required. Work must be carried out by hand and overseen by a qualified arborist.

Tree #	Species	DBH (cm)	Drip Line (m)	Condition Rating	Ownership	Action
755	honey locust (Gleditsia triacanthos)	38.5	7	Good	private	Protect. Prune large diameter dead branches.
756	honey locust (Gleditsia triacanthos)	31.5	6	Fair	private	Protect. Driveway widening inside minor portion of drip line. Work must be carried out by hand and overseen by a qualified arborist.
757	crabapple (Malus sp.)	17	3	Fair	private	Protect. Duct bank excavation inside drip line. Work must be carried out by hand and overseen by a qualified arborist.
758	crabapple (Malus sp.)	26	3.5	Poor	private	Protect.
759	crabapple (Malus sp.)	32	6	Good	private	Protect. Transformer pad and grading inside drip line. Work must be carried out by hand and overseen by a qualified arborist.
760	littleleaf linden (Tilia cordata)	44.5	4.5	Good	private	Protect.
761	littleleaf linden (Tilia cordata)	57.5	5	Good	private	Protect.
762	Colorado spruce (Picea pungens)	31.5	2	Poor	private	Protect.
763	honey locust (Gleditsia triacanthos)	25.5	4.5	Fair	private	Protect.
764	honey locust (Gleditsia triacanthos)	46	7	Fair	private	Protect. Prune large diameter dead branches.
765	Colorado spruce (Picea pungens)	26	3	Fair	private	Protect. Bicycle parking inside drip line. Perimeter of pad must be excavated by hand under arborist supervision.
766	littleleaf linden (Tilia cordata)	57	5.5	Good	private	Protect.
767	littleleaf linden (Tilia cordata)	64	6	Good	private	Protect.
768	honey locust (Gleditsia triacanthos)	44.5	6.5	Good	private	Protect.
769	sugar maple (Acer saccharum)	37	5	Fair	private	Protect.
770	pear (Pyrus sp.)	28, 22 (34)	4	Poor	private	Protect. Remove dead stem.
771	crabapple (Malus sp.)	25.5	4.5	Poor	private	Protect.
772	Austrian pine (Pinus nigra)	40	5.5	Fair	private	Protect.
773	Austrian pine (Pinus nigra)	38	3.5	Poor	private	Protect.
774	Austrian pine (Pinus nigra)	35.5	3.5	Fair	private	Protect.
775	Norway maple (Acer platanoides)	25	4.5	Poor	private	Protect. Prune large diameter dead branches.
776	black walnut (Juglans nigra)	53	8	Good	private	Protect.
777	honey locust (Gleditsia triacanthos)	24	3.5	Fair	private	Protect.
778	honey locust (Gleditsia triacanthos)	18.5	3	Fair	private	Protect.
779	Amur maple (Acer ginnala)	23	4	Fair	private	Protect.
780	Amur maple (Acer ginnala)	14	1	Poor	private	Protect.
781	Lilac (shrub) (Syringe vulgaris)	13.5, 12, 10	2.5	Fair	private	Protect. Not bylaw protected.
782	Amur maple (Acer ginnala)	15, 9, 8.5 (19)	3	Poor	private	Protect. Prune large diameter dead branches.
783	black walnut (Juglans nigra)	57	3.5	Good	private	Protect.
784	sugar maple (Acer saccharum)	27	6.5	Poor	private	Protect.
785	Austrian pine (Pinus nigra)	15	3.5	Poor	private	Protect.
786	Austrian pine (Pinus nigra)	35.5	3	Fair	private	Protect.
787	Amur maple (Acer ginnala)	16, 14.5, 14.5 (26)	4	Poor	private	Protect.
788	Amur maple (Acer ginnala)	15	2.5	Poor	private	Protect.
789	Amur maple (Acer ginnala)	20	4.5	Fair	private	Protect.
790	Amur maple (Acer ginnala)	22	2.5	Poor	private	Protect.
791	littleleaf linden (Tilia cordata)	55	6	Fair	private	Protect.
792	littleleaf linden (Tilia cordata)	61.5	6	Fair	private	Protect.
793	black walnut (Juglans nigra)	55	7	Good	private	Protect.
794	sugar maple (Acer saccharum)	33	4	Poor	private	Protect.
795	black walnut (Juglans nigra)	32		Dead	private	Protect. Recommend removal unrelated to project.
796	sugar maple (Acer saccharum)	41.5	7	Good	private	Protect.
797	black walnut (Juglans nigra)	30.5	5	Good	boundary (private & City-owned)	Protect.
798	pear (Pyrus sp.)	31.5	4	Poor	private	Protect.
799	Austrian pine (Pinus nigra)	29.5	1.5	Poor	private	Protect.
800	Austrian pine (Pinus nigra)	45	5	Fair	private	Protect.
801	Austrian pine (Pinus nigra)	32.5, 26 (42)	5	Fair	private	Protect.
802	sugar maple (Acer saccharum)	36	5	Good	private	Protect.
803	sugar maple (Acer saccharum)	30	4	Poor	private	Protect.
804	howsornbe (Crataegus sp.)	21, 19 (28)	3.5	Poor	private	Protect.
805	honey locust (Gleditsia triacanthos)	31	4	Fair	private	Protect.
806	black walnut (Juglans nigra)	37	4	Fair	private	Protect. Prune large diameter dead branches.
807	honey locust (Gleditsia triacanthos)	32.5	5	Good	private	Protect.
808	pear (Pyrus sp.)	20, 19 (35)	3	Poor	private	Protect. Recommend removal in near future.
809	Austrian pine (Pinus nigra)	24.5	2.5	Poor	private	Protect.

Tree #	Species	DBH (cm)	Drip Line (m)	Condition Rating	Ownership	Action
810	Austrian pine (Pinus nigra)	38	3.5	Fair	private	Protect.
811	Austrian pine (Pinus nigra)	40	4.5	Fair	private	Protect.
812	Colorado spruce (Picea pungens)	19	1.5	Poor	private	Protect.
813	Colorado spruce (Picea pungens)	6	1.5	Fair	private	Protect.
814	Colorado spruce (Picea pungens)	27.5	2.5	Poor	private	Protect.
815	Colorado spruce (Picea pungens)	22.5	2.5	Fair	private	Protect.
816	Colorado spruce (Picea pungens)	22.5	1.5	Poor	private	Protect.
817	Colorado spruce (Picea pungens)	23	2	Fair	private	Protect.
818	black walnut (Juglans nigra)	69	6	Fair	private	Protect.
819	black walnut (Juglans nigra)	38.5, 27.5 (47)	7	Fair	private	Protect.
820	black walnut (Juglans nigra)	66.5	5.5	Fair	private	Protect.
821	black walnut (Juglans nigra)	46.5	3	Poor	private	Protect. Prune large diameter dead branches.
822	honey locust (Gleditsia triacanthos)	16	2.5	Fair	private	Protect.
823	honey locust (Gleditsia triacanthos)	19	3	Good	private	Protect.
824	black walnut (Juglans nigra)	59	6	Fair	private	Protect.
825	black walnut (Juglans nigra)	36	5.5	Poor	private	Protect.
826	black walnut (Juglans nigra)	65	4.5	Fair	private	Protect.
827	black walnut (Juglans nigra)	61	5.5	Fair	private	Protect.
828	Colorado spruce (Picea pungens)	28	3	Poor	private	Protect.
829	sugar maple (Acer saccharum)	37.5	4.5	Good	private	Protect.
830	sugar maple (Acer saccharum)	31	4.5	Poor	private	Protect.
831	honey locust (Gleditsia triacanthos)	40	6	Good	boundary (private & City-owned)	Protect.
832	honey locust (Gleditsia triacanthos)	38	4.5	Good	boundary (private & City-owned)	Protect. Prune large diameter dead branches.
833	Austrian pine (Pinus nigra)	40.5	5	Good	private	Protect.
834	Austrian pine (Pinus nigra)	30.5	4	Fair	private	Protect.
835	Austrian pine (Pinus nigra)	39.5	4	Good	private	Protect.
836	honey locust (Gleditsia triacanthos)	38	6	Good	private	Protect.
837	honey locust (Gleditsia triacanthos)	37	6	Good	private	Protect. New sidewalk proposed inside drip line. Work must be carried out by hand and overseen by a qualified arborist.
838	Austrian pine (Pinus nigra)	27	2.5	Poor	private	Remove - proposed pedestrian walkway.
839	Austrian pine (Pinus nigra)	27	3.5	Fair	private	Remove - proposed pedestrian walkway.
840	Austrian pine (Pinus nigra)	43	5	Fair	private	Protect.
841	honey locust (Gleditsia triacanthos)	29.5	3.5	Poor	private	Protect.
842	honey locust (Gleditsia triacanthos)	42	6.5	Good	private	Protect. Prune large diameter dead branches.
843	Colorado spruce (Picea pungens)	22.5	3	Poor	private	Protect.
844	Colorado spruce (Picea pungens)	22.5	1.5	Poor	private	Protect.
845	honey locust (Gleditsia triacanthos)	52	9	Good	private	Protect. Existing parking lot curb and asphalt is to be removed and replaced with soft ground surface. Work inside the drip line must be overseen by a qualified arborist.
846	honey locust (Gleditsia triacanthos)	45.5	6	Good	private	Protect. Existing parking lot curb and asphalt is to be removed and replaced with soft ground surface. Work inside the drip line must be overseen by a qualified arborist.
847	littleleaf linden (Tilia cordata)	53	4.5	Poor	private	Remove due to poor structure and proximity to underground parking garage.
848	littleleaf linden (Tilia cordata)	40.5	7	Fair	private	Protect.
849	littleleaf linden (Tilia cordata)	55	6	Good	private	Remove due to underground parking excavation.
850	Colorado spruce (Picea pungens)	29	2.5	Poor	private	Remove - within footprint of underground parking.
851	staghorn sumac (Rhus typhina)	8	1	Fair	City-owned	Protect.
852	staghorn sumac (Rhus typhina)	8	1	Poor	City-owned	Protect.
853	staghorn sumac (Rhus typhina)	8	1	Poor	City-owned	Protect.
854	staghorn sumac (Rhus typhina)	8.5	1.5	Poor	City-owned	Protect.
855	staghorn sumac (Rhus typhina)	8	1	Poor	City-owned	Protect.
856	staghorn sumac (Rhus typhina)	8.5	1.5	Poor	City-owned	Protect.
857	staghorn sumac (Rhus typhina)	8.5	1.5	Poor	City-owned	Protect.
858	staghorn sumac (Rhus typhina)	8.5	1.5	Poor	City-owned	Protect.
859	Manitoba maple (Acer negundo)	24, 19, 13 (33)	3	Poor	City-owned	Protect.
860	Manitoba maple (Acer negundo)	23, 23 (32)	4	Fair	City-owned	Protect. Recommend pruning by City.
861	black walnut (Juglans nigra)	11	2	Fair	City-owned	Protect.
862	black walnut (Juglans nigra)	17	2.5	Fair	City-owned	Protect.
863	Manitoba maple (Acer negundo)	9.5	3.5	Poor	City-owned	Protect.
864	Manitoba maple (Acer negundo)	19	3.5	Fair	City-owned	Protect.
865	Manitoba maple (Acer negundo)	29	2.5	Poor	City-owned	Protect. Recommend removal by City, unrelated to project.

Tree #	Species	DBH (cm)	Drip Line (m)	Condition Rating	Ownership	Action
866	Manitoba maple (Acer negundo)	9	1.5	Poor	City-owned	Protect.
867	Manitoba maple (Acer negundo)	10	1.5	Poor	City-owned	Protect.
868	Manitoba maple (Acer negundo)	11	1.5	Fair	City-owned	Protect.
869	Manitoba maple (Acer negundo)	31	3	Poor	City-owned	Protect. Recommend pruning by City.
870	Norway maple (Acer platanoides)	24	3.5	Fair	City-owned	Protect.
871	Manitoba maple (Acer negundo)	26.5	2.5	Fair	City-owned	Protect.
872	Amur maple (Acer ginnala)	8.5	1.5	Poor	City-owned	Protect.
873	staghorn sumac (Rhus typhina)	11	2	Poor	boundary (private & City-owned)	Protect.
874	Amur maple (Acer ginnala)	12	1.5	Fair	boundary (private & City-owned)	Protect.
875	Manitoba maple (Acer negundo)	19	4	Poor	private	Protect.
876	Manitoba maple (Acer negundo)	14.5	2.5	Fair	private	Protect.
877	green ash (Fraxinus)	10	2	Good	private	Protect. Recommend removal by City, unrelated to project.
8						