
SOIL-MAT ENGINEERS & CONSULTANTS LTD.

www.soil-mat.ca info@soil-mat.ca TF: 800.243.1922

Hamilton: 130 Lancing Drive L8W 3A1 T: 905.318.7440 F: 905.318.7455

Milton: PO Box 40012 Derry Heights PO L9T 7W4 T: 800.243.1922



PROJECT No.: SM 190492-G

August 8, 2019

THE CITY OF MISSISSAUGA
300 City Centre Drive
Mississauga, Ontario
L5B 3C1

**RELIANCE LETTER
GEOTECHNICAL AND ENVIRONMENTAL ASSESSMENT REPORTS
86-90 DUNDAS STREET EAST
MISSISSAUGA, ONTARIO**

As requested by Mr. Jeff Murva of EMBLEM DEVELOPMENTS CORP [EMBLEM], please consider this letter as our acknowledgement of THE CITY OF MISSISSAUGA [MISSISSAUGA] relying on the following SOIL-MAT ENGINEERS & CONSULTANTS LTD. ["SOIL-MAT ENGINEERS"] Reports.

1. SOIL-MAT ENGINEERS Report No.: SM 124461-E [Phase One Environmental Site Assessment, 86-90 Dundas Street East, Mississauga, Ontario, dated October 22, 2012]
2. SOIL-MAT ENGINEERS Report No.: SM 124461-E [Phase Two Environmental Site Assessment, 86-90 Dundas Street East, Mississauga, Ontario, dated November 27, 2012]
3. SOIL-MAT ENGINEERS Report No.: SM 124462-G [Geotechnical Investigation, 86-90 Dundas Street East, Mississauga, Ontario, dated November 27, 2012]
4. SOIL-MAT ENGINEERS Report No.: SM 166913-G [Slope Stability Assessment, 86-90 Dundas Street East, Mississauga, Ontario, dated August 4, 2016]
5. SOIL-MAT ENGINEERS Report No.: SM 166913-G [Slope Stability Comments, 86-90 Dundas Street East, Mississauga, Ontario, dated May 11, 2017]
6. SOIL-MAT ENGINEERS Report No.: SM 177568-E [Phase One Environmental Site Assessment Update, 86-90 Dundas Street East, Mississauga, Ontario, dated July 17, 2017]
7. SOIL-MAT ENGINEERS Report No.: SM 177569-E [Supplemental Phase Two Environmental Site Assessment, 86-90 Dundas Street East, Mississauga, Ontario, dated November 30, 2017]
8. SOIL-MAT ENGINEERS Report No.: SM 166913-G [Supplemental Geotechnical Comments, Proposed 29-Storey Building, 86-90 Dundas Street East, Mississauga, Ontario, dated April 3, 2018]
9. SOIL-MAT ENGINEERS Report No.: SM 166913-G [Slope Stability Assessment – Supplemental Report, Proposed High-Rise Condominium Building, 86-90 Dundas Street East, Mississauga, Ontario, dated September 20, 2018]



10. SOIL-MAT ENGINEERS Report No.: SM 177569-G [Environmental Considerations, Proposed High-Rise Condominium Building, 86-90 Dundas Street East, Mississauga, Ontario, dated September 20, 2018]

It is noted that the referenced reports were originally prepared for the owner(s) at the time the respective reports were completed, and further understood that ownership and use transferred to EMBLEM as part of their acquisition of the project. The above noted Reports may be relied upon by EMBLEM and/or MISSISSAUGA to the same extent as the original client except that our potential liability to EMBLEM and MISSISSAUGA arising out of the report is limited to the amount of professional liability insurance coverage maintained to a maximum of one million dollars or the loan amount, whichever is less, regardless of any limitation on liability agreed to by our client. It is further understood and agreed that SOIL-MAT ENGINEERS shall be retained for all interpretation in the event that EMBLEM and/or MISSISSAUGA have any questions with respect to the content of the Reports.

We trust that this information is satisfactory for your purposes. Should you have any queries please do not hesitate to contact the undersigned directly.

Yours very truly,
SOIL-MAT ENGINEERS & CONSULTANTS LTD.

A handwritten signature in blue ink, appearing to read "I. Shaw".

Ian Shaw, P.Eng., QP_{ESA}
Senior Engineer

Distribution: EMBLEM DEVELOPMENTS CORP [1, pdf by email]
WESTON CONSULTING [1, pdf by email]